



様

### 森寺の振興に関するお願ひ

日頃より、森寺の振興に心温かいご支援を賜り感謝申し上げます。私どもも、『市民と一緒に政策をつくり上げていく地域づくり』に共感し、村民一丸となり安全安心で元気な村づくりに取り組んでゆく所存であります。つきましては、次項に掲げる諸課題について引き続きご支援ご協力を賜りますようお願ひ申し上げます。

平成26年6月23日

森寺自治会



堀口 八郎

瀬戸 正次

### 【最近の森寺活動の紹介】

森寺獅子 新市庁舎開庁を祝いました。



森寺城跡の環境を整え、ゴールデンウイーク中も沢山の来訪者を迎えるました。




## 森寺懸案事項

事 項	防火水槽の新設
内 容	森寺第6班(11所帯)では、防火用水として森寺用水に依存しているが水量が少ないと加え、同用水は山麓を蛇行して来ることから欠落断水の懼れがあり、防火対策への不安を抱えている。
状況写真	
位 置	

## 森寺懸案事項


事 項	市道 親田川橋台の変形
内 容	右岸橋台にクッラック発生、袖土止め壁の傾倒
状 況 写 真	



## 森寺懸案事項

事項	市道 ふるさと歩道路舗装欠損
内容	森寺城址登り口 ふるさと歩道路肩陥落のため舗装の欠損(約30m)、森寺用水路への影響も懸念される
状況写真	 
位置	

## 森寺懸案事項

事 項	市道 親田線路肩、舗装の変形
内 容	市道 親田～城址線の森寺墓地下のカーブ付近にて路肩の変形に伴い舗装の沈下(約30m)が著しい。
状況写真	 <p>A photograph of a paved road curving through a wooded area. The shoulder of the road is eroded and collapsed, with a significant depression. A utility pipe is visible on the right side of the road. Labels indicate '路肩沈下' (shoulder沉下) pointing to the collapsed shoulder, '舗装沈下' (paving沉下) pointing to the depression in the asphalt, and '用水パイプ' (water pipe) pointing to the pipe.</p>
位 置	 <p>A map of the area around the Kiyomori Mausoleum. A specific location on the '親田線' (Kin田 line) is highlighted with a box and labeled '親田線舗装沈下' (subsidence of paving on the Kin田 line). The map shows the surrounding terrain, roads, and buildings.</p>